

Tool list

Sorted by position in WinTool list

100 1050 - 20 C_clamping equip.
B clamping equip.


Side frame left
O-1113-M1

6/24/2010
Aluminium

T 1 clamping plate 800x400x32 mm
726001 drill hole grid 20-M10

D
H

Quantity	Component	Item No
1	clamping plate 800x400x32 mm	51312



T 2 tensioning hook
726003 SB 100

D
H

Quantity	Component	Item No
1	tensioning hook	51313



T 3 guide bar
726005 FL 50x30x30

D
H

Quantity	Component	Item No
1	guide bar	51317



T 4 tensioning hook
726003 SB 100

D
H

Quantity	Component	Item No
1	tensioning hook	51313



T 5 guide bar
726005 FL 50x30x30

D
H

Quantity	Component	Item No
1	guide bar	51317



Tool list

Sorted by position in WinTool list

T 6 tensioning hook
726003 SB 100

D
H

Quantity	Component	Item No
1	tensioning hook	51313



T 7 guide bar
726005 FL 50x30x30

D
H

Quantity	Component	Item No
1	guide bar	51317



T 8 permanent block
726004 SBP 70

D
H

Quantity	Component	Item No
1	permanent block	51314



T 9 stop bolt
726006 BZ 14x5,4

D
H

Quantity	Component	Item No
1	stop bolt	51318



T 10 claw tensioning element
726002 SB 120-68

D
H

Quantity	Component	Item No
1	claw tensioning element	51316



Tool list

Sorted by position in WinTool list

T 11 guide bar
726005 FL 50x30x30

D
H

Quantity	Component	Item No
1	guide bar	51317

